
Section 22 Connecticut

Appendix J

Connecticut Coastal Structures Inventory Study - Phase II

July 1989



**US Army Corps
of Engineers**
New England Division

REPORT DOCUMENTATION PAGE			Form Approved OMB No. 0704-0188	
<small>Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.</small>				
1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE July 1989	3. REPORT TYPE AND DATES COVERED Section 22		
4. TITLE AND SUBTITLE Section 22, Connecticut Coastal Structures Inventory Study, Phase II, Appendix J, Branford Quadrangle, Records of Structures With Photographs			5. FUNDING NUMBERS	
6. AUTHOR(S) U.S. Army Corps of Engineers New England Division				
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Corps of Engineers, New England Division 424 Trapelo Road Waltham, MA 02254-9149			8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) Connecticut Department of Environmental Protection Coastal Resources Management Division			10. SPONSORING / MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES				
12a. DISTRIBUTION / AVAILABILITY STATEMENT Approved for public release Distribution is unlimited			12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) This Appendix J report contains data gathered during Phase II of the ongoing project to inventory erosion and flood control structures on the northern shore of Long Island Sound within the statutory boundaries of the State of Connecticut. Included are the record of information on each structure and photographs for each structure.				
14. SUBJECT TERMS Branford Quadrangle; coastal regions; structures			15. NUMBER OF PAGES 118	
			16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	20. LIMITATION OF ABSTRACT	

GENERAL INSTRUCTIONS FOR COMPLETING SF 298

The Report Documentation Page (RDP) is used in announcing and cataloging reports. It is important that this information be consistent with the rest of the report, particularly the cover and title page. Instructions for filling in each block of the form follow. It is important to *stay within the lines* to meet optical scanning requirements.

Block 1. Agency Use Only (Leave blank).

Block 2. Report Date. Full publication date including day, month, and year, if available (e.g. 1 Jan 88). Must cite at least the year.

Block 3. Type of Report and Dates Covered. State whether report is interim, final, etc. If applicable, enter inclusive report dates (e.g. 10 Jun 87 - 30 Jun 88).

Block 4. Title and Subtitle. A title is taken from the part of the report that provides the most meaningful and complete information. When a report is prepared in more than one volume, repeat the primary title, add volume number, and include subtitle for the specific volume. On classified documents enter the title classification in parentheses.

Block 5. Funding Numbers. To include contract and grant numbers; may include program element number(s), project number(s), task number(s), and work unit number(s). Use the following labels:

C - Contract	PR - Project
G - Grant	TA - Task
PE - Program Element	WU - Work Unit Accession No.

Block 6. Author(s). Name(s) of person(s) responsible for writing the report, performing the research, or credited with the content of the report. If editor or compiler, this should follow the name(s).

Block 7. Performing Organization Name(s) and Address(es). Self-explanatory.

Block 8. Performing Organization Report Number. Enter the unique alphanumeric report number(s) assigned by the organization performing the report.

Block 9. Sponsoring/Monitoring Agency Name(s) and Address(es). Self-explanatory.

Block 10. Sponsoring/Monitoring Agency Report Number. (If known)

Block 11. Supplementary Notes. Enter information not included elsewhere such as: Prepared in cooperation with...; Trans. of...; To be published in.... When a report is revised, include a statement whether the new report supersedes or supplements the older report.

Block 12a. Distribution/Availability Statement. Denotes public availability or limitations. Cite any availability to the public. Enter additional limitations or special markings in all capitals (e.g. NOFORN, REL, ITAR).

DOD - See DoDD 5230.24, "Distribution Statements on Technical Documents."

DOE - See authorities.

NASA - See Handbook NHB 2200.2.

NTIS - Leave blank.

Block 12b. Distribution Code.

DOD - Leave blank.

DOE - Enter DOE distribution categories from the Standard Distribution for Unclassified Scientific and Technical Reports.

NASA - Leave blank.

NTIS - Leave blank.

Block 13. Abstract. Include a brief (Maximum 200 words) factual summary of the most significant information contained in the report.

Block 14. Subject Terms. Keywords or phrases identifying major subjects in the report.

Block 15. Number of Pages. Enter the total number of pages.

Block 16. Price Code. Enter appropriate price code (NTIS only).

Blocks 17.-19. Security Classifications. Self-explanatory. Enter U.S. Security Classification in accordance with U.S. Security Regulations (i.e., UNCLASSIFIED). If form contains classified information, stamp classification on the top and bottom of the page.

Block 20. Limitation of Abstract. This block must be completed to assign a limitation to the abstract. Enter either UL (unlimited) or SAR (same as report). An entry in this block is necessary if the abstract is to be limited. If blank, the abstract is assumed to be unlimited.

SECTION 22
CONNECTICUT COASTAL STRUCTURES INVENTORY STUDY
PHASE II

APPENDIX J
BRANFORD QUADRANGLE

RECORDS OF STRUCTURES WITH PHOTOGRAPHS

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

JULY 1989

INVENTORY NUMBER: 1.00

QUAD : BRANFORD
ADDRESS: FLYING POINT ROAD
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO STONE BLOCKS. APROX L= 1100 FT, W= 2 FT, H= 3-5 FT
ABOVE MHW.

INSPECTION DATE : 08/10/88 INSPECTION TIME: 1354

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 2 LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

NO SHORE

BR 1.00 #1



INVENTORY NUMBER: 2.00

QUAD : BRANFORD
ADDRESS: RAND'S POINT
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 1600 FT, W= 2 FT, H= 1-4 FT ABOVE MHW

INSPECTION DATE : 08/10/88 INSPECTION TIME: 1412

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 3 LOOKING SOUTHEAST FROM DOCK
#2
#3
#4
#5

COMMENTS

SEAWALL INTERRUPTED BY BEDROCK. SHORE COMPOSED OF EXPOSED
BEDROCK.

BR 2.00 #1



INVENTORY NUMBER: 3.00

QUAD : BRANFORD
ADDRESS: LINDEN POINT ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: FAIR
MAIN FUNCTION : PROTECTIVE LAYER WHICH PREVENTS EROSION OF A SLOP
MATERIAL : LARGE BOULDERS

DESCRIPTION

APROX L= 600 FT, W= 25 FT, H= 0-2 FT ABOVE MHW

INSPECTION DATE : 08/10/88 INSPECTION TIME: 1423

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 4 LOOKING NORTH FROM DOCK
#2
#3
#4
#5

COMMENTS

NO SHORE. AREA OF EXPOSED BEDROCK.

BR 3.00 #1



INVENTORY NUMBER: 4.00

QUAD : BRANFORD
ADDRESS: THIMBLES ISLAND ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 800 FT, W= 2 FT, H= 4-6 FT ABOVE MHW

INSPECTION DATE : 08/10/88 INSPECTION TIME: 1430

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : AMERICA'S CUP RESTAURANT
ACCESS : PRIVATE
LAND USE : RECREATIONAL/COMMERCIAL

- PHOTOS -

#1 ROLL 42 NEG 5 LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

NO SHORE. AREA OF EXPOSED BEDROCK.

SR 4.00 #1



INVENTORY NUMBER: 5.00

QUAD : BRANFORD
ADDRESS: THIMBLES ISLAND ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 200 FT, W= 2 FT, H= 1 FT ABOVE MHW

INSPECTION DATE : 08/10/88 INSPECTION TIME: 1457

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE - TOWN PROPERTY
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 42 NEG 7 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

MARSHY AREA TO NORTH

6R 5.00 #1



INVENTORY NUMBER: 6.00

QUAD : BRANFORD
ADDRESS: HALLS POINT ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO CONCRETE. APROX L= 400 FT, W= 1-2 FT, H= 2-7 FT ABOVE
MHW.

INSPECTION DATE : 08/10/88 INSPECTION TIME: 1440

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 6 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

NO SHORE

BR 6.00 #1



INVENTORY NUMBER: 7.00

QUAD : BRANFORD
ADDRESS: PLEASANT POINT ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL/BLKHEAD CONDITION: GOOD
MAIN FUNCTION : RETAINS LAND THAT INDUSTRIAL FACILITY IS LOCATED
MATERIAL : STEEL PILE

DESCRIPTION

AND CEMENT BLOCKS. HAS RIPRAP IN FRONT. APROX L= 400 FT,
H= 2-8 FT ABOVE MHW

INSPECTION DATE : 08/10/88 INSPECTION TIME: 1553

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : TILCON TOMASCO
ACCESS : PRIVATE
LAND USE : INDUSTRIAL

- PHOTOS -

#1 ROLL 42 NEG 8 LOOKING WEST
#2
#3
#4
#5

COMMENTS

TILCONTOMASCO - GROUND AND CRUSHED STONE LOADED ONTO BARGES.
NO SHORE.

BR 7.00 #1



INVENTORY NUMBER: 8.00

QUAD : BRANFORD
ADDRESS: 395 PINE ORCHARD ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : TRAPS SAND, RETARDS SHORE EROSION
MATERIAL :

DESCRIPTION

APROX L= 55 FT, W= 2.5 FT, H= 1-3 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 901

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 42 NEG 9 LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY WITH EXPOSED BEDROCK

BR 3.00 #1



INVENTORY NUMBER: 9.00

QUAD : BRANFORD
ADDRESS: PINE ORCHARD ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 180 FT, W= 11 FT, H= 5 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 902

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 10 SEAWALL LOOKING WEST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY BEACH BETWEEN GROINS. REBUILT SINCE HURRICANE GLORIA.

SR 9.00 #1



INVENTORY NUMBER: 10.00

QUAD : BRANFORD
ADDRESS: PINE ORCHARD ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: POOR
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 71 FT, W= 0.5 FT, H= 0-3 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 914

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 42 NEG 11 GROIN FROM BASE
#2
#3
#4
#5

COMMENTS

SANDY BEACH BETWEEN GROINS

BR 10.00 #1



INVENTORY NUMBER: 11.00

QUAD : BRANFORD
ADDRESS: 2 PARK DRIVE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : RETAINS LAND, PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 227 FT, W= 1.5 FT, H= 4 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 923

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PINE ORCHD YACHT SQUADRON
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 42 NEG 12 BULKHEAD LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

NO SHORE - MOORING AREA FOR BOATS

BR 11.00 #1



INVENTORY NUMBER: 12.00

QUAD : BRANFORD
ADDRESS: BRANDGEE-ISLAND VIEW AVE.
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO STEEL PILE AND CONCRETE. APROX L= 1600 FT, W= 2-3 FT,
H= 2-5 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 928

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 13 BEGINNING OF SEAWALL - EAST SIDE
#2 ROLL 42 NEG 15 SEAWALL WEST SIDE
#3
#4
#5


COMMENTS

EXTENDS FROM BROWNS POINT. SAND SHORE WITH SMALL COBBLES.

BR 12.00 #1



BR 12.00 #2



INVENTORY NUMBER: 13.00

QUAD : BRANFORD
ADDRESS: BROWN POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS HARBOR/ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 650 FT, W= 12 FT, H= 3 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 935

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL

- PHOTOS -

#1 ROLL 42 NEG 14 LOOKING SOUTHEAST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY

BR 13.00 #1



INVENTORY NUMBER: 14.00

QUAD : BRANFORD
ADDRESS: HALSTEAD LAND
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: 3 GROINS CONDITION: FAIR
MAIN FUNCTION : TRAPS SAND, RETARDS SHORE EROSION
MATERIAL : WOOD

DESCRIPTION

APROX L= 60 FT, W= 4.5 FT, H= 0 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 959

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 16 GROINS LOOKING WEST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY

BR 14.00 #1



INVENTORY NUMBER: 15.00

QUAD : BRANFORD
ADDRESS: HALSTEAD LANE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: GOOD
MAIN FUNCTION : PROTECTIVE LAYER ON A SLOPE WHICH PREVENTS EROSION
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 750 FT, W= 20-25 FT, H= 15-20 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 960

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 17 RIPRAP LOOKING WEST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY WITH SMALL COBBLES

BR 15.00 #1



J30

INVENTORY NUMBER: 16.00

QUAD : BRANFORD
ADDRESS: PINE ORCHARD ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 1100 FT, W= 3 FT, H= 5 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1018

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 18 SEAWALL LOOKING WEST
#2 ROLL 42 NEG 19 SEAWALL LOOKING WEST
#3
#4
#5

COMMENTS

SHORE VARIES FROM NO SHORE TO EXPOSED BEDROCK TO SMALL
COBBLE BEACH.

BR 16.00 #1



BR 16.00 #2



INVENTORY NUMBER: 17.00

QUAD : BRANFORD
ADDRESS: FIRST AVENUE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 450 FT, W= 2 FT, H= 7 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1043

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : HOTCHKIS GROVE BEACH
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 42 NEG 20 LOOKING EAST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY

BR 17.00 #1



INVENTORY NUMBER: 18.00

QUAD : BRANFORD
ADDRESS: SEAVIEW AVE TO HAYCOCK PT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR-POOR
MAIN FUNCTION : PREVENTS FLOODING AND EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO STONE BLOCKS AND CONCRETE. APROX L= 2300 FT, W= 2-5 FT
H= 2-10 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1103

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL

- PHOTOS -

#1 ROLL 42 NEG 21 LOOKING EAST
#2 ROLL 42 NEG 22 LOOKING SOUTHWEST
#3 ROLL 42 NEG 24 LOOKING EAST
#4
#5


COMMENTS

SHORE: VARIES. SANDY BEACH FOR RECREATION AT HOTCHKIS GROVE
BEACH. NO BEACH IN FRONT OF HOUSES.

BR 18.00 #1



BR 13.00 #2



BR 13.00 #3



J36

INVENTORY NUMBER: 19.00

QUAD : BRANFORD
ADDRESS: HAYCOCK POINT ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO CONCRETE. APROX L= 150 FT, W= 6 FT, H= 3 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1116

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : HAYCOCK POINT BEACH
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 42 NEG 23 LOOKING SOUTHEAST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY BEACH. THEY BRING IN A TRUCK LOAD EACH YEAR.

3R 19.00 #1



INVENTORY NUMBER: 20.00

QUAD : BRANFORD
ADDRESS: ROUTE 146
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL/REVTMNT CONDITION: FAIR
MAIN FUNCTION : PROTECTS SLOPE FROM EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

SEAWALL OF JERSY BARRIERS ALONG ROAD ABOVE REVETMENT. APROX
L= 600 FT, W= 17 FT, H= 5 FT ABOVE MHW.

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1127

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 43 NEG 1 REVETMENT LOOKING EAST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY SHORE AT LIMWOOD BEACH, BUT NO SHORE ALONG
REKETMENT.

BR 20.00 #1



INVENTORY NUMBER: 21.00

QUAD : BRANFORD
ADDRESS: ROUTE 146
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: POOR
MAIN FUNCTION : TRAPS LITTORAL DRIFT
MATERIAL : TIMBER PILE

DESCRIPTION

APROX L= 42 FT, W= 1 FT, H= 0-1 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1133

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 43 NEG 2 LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

NO SHORE

BR 21.00 #1



INVENTORY NUMBER: 22.00

QUAD : BRANFORD
ADDRESS: ROUTE 146
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL
MAIN FUNCTION : PREVENTS EROSION
MATERIAL : STONE IN CEMENT

CONDITION: GOOD-POCR

DESCRIPTION

ALSO CONCRETE AND STEEL PILE. APROX L= 1300 FT, W= 2-6 FT
H= 6-10 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1145

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 43 NEG 3 LOOKING SOUTHWEST
#2 ROLL 43 NEG 6 LOOKING WEST FROM BREAKWATER
#3
#4
#5


COMMENTS

SHORE: VARIES FROM EXPOSED BEDROCK TO SANDY BEACH

BR 22.00 #1



BR 22.00 #2



INVENTORY NUMBER: 23.00

QUAD : BRANFORD
ADDRESS: SOUND VIEW HEIGHTS
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: 2 GROINS CONDITION: FAIR
MAIN FUNCTION : TRAPS SAND, RETARDS SHORE EROSION
MATERIAL : WOOD

DESCRIPTION

APROX L= 50 FT, W= 1-3.5 FT, H= 0-2 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1155

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : SOUNDVIEW HEIGHTS ASSOC.
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 43 NEG 4 LOOKING EAST AT FIRST GROIN
#2 ROLL 43 NEG 5 LOOKING SOUTHWEST AT SECOND GROIN
#3
#4
#5


COMMENTS

NO SHORE

BR 23.00 #1



BR 23.00 #2



INVENTORY NUMBER: 24.00

QUAD : BRANFORD
ADDRESS: SOUND VIEW HEIGHTS
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: POOR
MAIN FUNCTION : PROTECTS ANCHORAGE
MATERIAL : STONE BLOCKS

DESCRIPTION

ALSO STEEL PILE AND CONCRETE. APROX L= 120 FT, W= 16 FT
H= 5 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1203

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 43 NEG 7 LOOKING EAST
#2
#3
#4
#5

COMMENTS

NO SHORE TO EAST. SANDY SHORE ON WEST IN FRONT OF OWENEGO
YACHT CLUB. SEAWALL IN FRONT OF YACHT CLUB NEW LAST YEAR.

BR 24.00 #1



INVENTORY NUMBER: 25.00

QUAD : BRANFORD
ADDRESS: LINDEN ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: POOR
MAIN FUNCTION : TRAPS LITTORAL DRIFT
MATERIAL : STEEL

DESCRIPTION

APROX L= 35 FT, W= 1 FT, H= 0-2 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1212

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : OWENEGO YACHT CLUB
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 43 NEG 8 LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

SHORE: SAND TO WEST OF GROIN

BR 25.00 #1



INVENTORY NUMBER: 26.00

QUAD : BRANFORD
ADDRESS: RTE 146/OPP. PAWSON ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: FAIR
MAIN FUNCTION : TRAPS SAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

CONCRETE CAP. APROX L= 98 FT, W= 5 FT, H= 3 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1321

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : LINDEN SHORE DISTRICT
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 43 NEG 9 LOOKING EAST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY WITH SOME EXPOSED BEDROCK

BR 26.00 #1



INVENTORY NUMBER: 27.00

QUAD : BRANFORD
ADDRESS: ROUTE 146
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: FAIR
MAIN FUNCTION : TRAPS LITTORAL DRIFT
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 144 FT, W= 10 FT, H= 5 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1334

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : LINDEN BEACH DISTRICT
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL


- PHOTOS -

#1 ROLL 43 NEG 10 LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY

BR 27.00 #1



INVENTORY NUMBER: 28.00

QUAD : BRANFORD
ADDRESS: LINDEN POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL/BLKHEAD CONDITION: POOR
MAIN FUNCTION : RETAINS LAND, PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 325 FT, W= 1 FT, H= 5 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1355

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 43 NEG 12 LOOKING EAST
#2
#3
#4
#5

COMMENTS

NO SHORE

BR 28.00 #1



INVENTORY NUMBER: 29.00

QUAD : BRANFORD
ADDRESS: BAYBERRY LN/SUMMER IS. RD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD-FAIR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO STONE BLOCKS AND CONCRETE. APROX L= 2000 FT, W= 1-7 FT
H= 2-6 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1349

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 43 NEG 11 LOOKING NORTHWEST
#2 ROLL 43 NEG 13 LOOKING WEST
#3
#4
#5

COMMENTS

NO SHORE IN FRONT OF SEAWALL ON EAST SIDE. ON WEST SIDE
SOME SANDY SHORE NEAR BREAKWATER. MARSHY AREA IN COVE.

BR 29.00 #1



BR 29.00 #2



INVENTORY NUMBER: 30.00

QUAD : BRANFORD
ADDRESS: SUMMER ISLAND ROAD EXTEN.
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS ANCHORAGE
MATERIAL : STONE/CEMNT CAP

DESCRIPTION

APROX L= 90 FT, W= 10 FT, H= 3 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1409

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 43 NEG 14 LOOKING WEST
#2
#3
#4
#5

COMMENTS

BR 30.00 #1



INVENTORY NUMBER: 31.00

QUAD : BRANFORD
ADDRESS: SUNSET BEACH ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : PREVENTS EROSION
MATERIAL : STONE BLOCKS

DESCRIPTION

ALSO TIMBER PILE. APROX L= 1100 FT, W= 1-3 FT, H= 0-4 FT
ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1433

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 43 NEG 17 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

SEAWALL EXTENDS FROM CHANNEL OF STREAM AROUND POINT.

BR 31.00 #1



INVENTORY NUMBER: 32.00

QUAD : BRANFORD
ADDRESS: JEFFERY POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO CONCRETE. APROX L= 800 FT, W= 1-2 FT, H= 4-7 FT ABOVE
MHW.

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1423

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 43 NEG 15 BEGINNING OF SEAWALL LOOKING NORTH
#2 ROLL 43 NEG 16 SEAWALL AT POINT LOOKING SOUTH
#3 ROLL 43 NEG 18 SEAWALL NORTH OF JEFFERY POINT
#4
#5

COMMENTS

EXPOSED BEDROCK AND MARSHY AREAS

BR 32.00 #1



BR 32.00 #2



BR 32.00 #3



INVENTORY NUMBER: 33.00

QUAD : BRANFORD
ADDRESS: SUNSET BEACH ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO CONCRETE. APROX L= 200 FT, W= 1 FT, H= 4-8 FT ABOVE
MHW.

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1505

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : SUNSET BEACH
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL


- PHOTOS -

#1 ROLL 43 NEG 20 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY WITH SMALL COBBLES

BR 33.00 #1



INVENTORY NUMBER: 34.00

QUAD : BRANFORD
ADDRESS: SUNSET BEACH ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: FAIR
MAIN FUNCTION : RETAINS LAND, PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO CONCRETE. APROX L= 400 FT, W= 1.5 FT, H= 4-6 FT ABOVE
MHW.

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1459

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 43 NEG 19 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY WITH SMALL PEBBLES

BR 34.00 #1



INVENTORY NUMBER: 35.00

QUAD : BRANFORD
ADDRESS: BRANFORD PT./HARBOR ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: JETTY CONDITION: GOOD
MAIN FUNCTION : PROTECTS ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : STONE BLOCKS

DESCRIPTION

CAPPED WITH ASPHALT. APROX L= 200 FT, W= 60 FT, H= 4 FT
ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1550

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : BRANFORD POINT
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 43 NEG 21 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

PROTECTS HARBOR IN BRANFORD RIVER

BR 35.00 #1



INVENTORY NUMBER: 36.00

QUAD : BRANFORD
ADDRESS: HARBOR ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION AND SLIDING OF BANK
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 450 FT, W= 3 FT, H= 8-10 FT ABOVE MHW

INSPECTION DATE : 08/11/88 INSPECTION TIME: 1557

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : TOWN OF BRANFORD
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 43 NEG 22 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

SHORE: SANDY BEACH

BR 36.00 #1



INVENTORY NUMBER: 37.00

QUAD : BRANFORD
ADDRESS: SUNRISE COVE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : PREVENTS FLOODING, RETAINS LAND
MATERIAL : CONCRETE

DESCRIPTION

APROX L= 250 FT, W= 1-2 FT, H= 1-5 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 925

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL

- PHOTOS -

#1 ROLL 43 NEG 23 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

SANDY COVE

BR 37.00 #1



INVENTORY NUMBER: 38.00

QUAD : BRANFORD
ADDRESS: 100 DOUBLE BEACH ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR-POOR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 60 FT, W= 2 FT, H= 11 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1010

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : ECHLIN, INC.
ACCESS : PRIVATE
LAND USE : INDUSTRIAL

- PHOTOS -

#1 ROLL 43 NEG 24 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

CORPORATE HEADQUARTERS - BOUGHT PROPERTY IN 1979



INVENTORY NUMBER: 39.00

QUAD : BRANFORD
ADDRESS: TURTLE COVE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : FACING ON SLOPE WHICH PREVENTS EROSION
MATERIAL : IRR. STONE FRAG

DESCRIPTION

APROX L= 195 FT, W= 10 FT, H= 13 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1030

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : TURTLE COVE ASSOCIATION
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 1 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

MARSHY SHORE

BR 39.00 #1



INVENTORY NUMBER: 40.00

QUAD : BRANFORD
ADDRESS: TURTLE COVE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 300 FT, W= 4 FT, H= 10-12 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1035

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : TURTLE COVE ASSOCIATION
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 2,3 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

NO SHORE



BR 40.00 #1

VACANT

INVENTORY NUMBER: 41.00

QUAD : BRANFORD
ADDRESS: JOHNSON'S POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 105 FT, W= 14 FT, H= 3 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1052

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : JOHNSON'S POINT ASSOC.
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 4 BREAKWATER LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

SHORE: EXPOSED BEDROCK

BR 41.00 #1



INVENTORY NUMBER: 42.00

QUAD : BRANFORD
ADDRESS: JOHNSON'S POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

HAS RIPRAP IN FRONT. APROX L= 220 FT, W= 2 FT, H= 4 FT
ABOVE MHW.

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1128

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : JOHNSON'S POINT ASSOC.
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 5 LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

SHORE: EXPOSED BEDROCK

BR 42.00 #1



INVENTORY NUMBER: 43.00

QUAD : BRANFORD
ADDRESS: JOHNSON'S POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : RETAINS LAND, PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 230 FT, W= 1.5-2 FT, H= 4-13 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1139

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : JOHNSON'S POINT ASSOC.
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 6 LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

SHORE: EXPOSED BEDROCK WITH SOME MARSHY AREAS.

BR 43.00 #1



INVENTORY NUMBER: 44.00

QUAD : BRANFORD
ADDRESS: JOHNSON'S POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: FAIR
MAIN FUNCTION : RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 125 FT, W= 1.5 FT, H= 7 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1146

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : JOHNSON'S POINT ASSOC.
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 7 LOOKING SOUTHEAST
#2
#3
#4
#5

COMMENTS

EXPOSED BEDROCK AT POINT

BR 44.00 #1



INVENTORY NUMBER: 45.00

QUAD : BRANFORD
ADDRESS: JOHNSON'S POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS HARBOR/ANCHORAGE
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 30 FT, W= 25 FT, H= 6 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1152

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : JOHNSON'S POINT ASSOC.
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 8 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

SHORE: EXPOSED BEDROCK

ER 45.00 #1



INVENTORY NUMBER: 46.00

QUAD : BRANFORD
ADDRESS: KILMAN'S POINT
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION, RETAINS LAND
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 140 FT, W= 2.5 FT, H= 9 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1310

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 9 SEAWALL LOOKING EAST
#2
#3
#4
#5

COMMENTS

SOME SAND, MARSH, AND EXPOSED BEDROCK



INVENTORY NUMBER: 47.00

QUAD : BRANFORD
ADDRESS: KILMAN POINT ROAD
TOWN : BRANFORD
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION, RETAINS ROADWAY TO POINT
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 300 FT, W= 1.5-2 FT, H= 2-3 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1325

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 10 LOOKING EAST
#2
#3
#4
#5

COMMENTS

NO SHORE

BR 47.00 #1



INVENTORY NUMBER: 48.00

QUAD : BRANFORD
ADDRESS: 302 SHORE DRIVE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: FAIR
MAIN FUNCTION : PROTECTIVE LAYER WHICH PREVENTS EROSION OF A ROAD
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 285 FT, W= 20 FT, H= 4-5 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1331

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : GRANITE BAY - OFF ROAD
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/ROADWAY

- PHOTOS -

#1 ROLL 44 NEG 11 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

SHORE: SAND, MARSH, AND EXPOSED BEDROCK



INVENTORY NUMBER: 49.00

QUAD : BRANFORD
ADDRESS: SHORE DRIVE/PAGES COVE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 600 FT, W= 2 FT, H= 5 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1350

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 12 LOOKING WEST
#2
#3
#4
#5

COMMENTS

NO SHORE

BR 49.00 #1



INVENTORY NUMBER: 50.00

QUAD : BRANFORD
ADDRESS: STANLEY POINT/SHORE DRIVE
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION AND FLOODING, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO STONE BLOCKS AND CONCRETE. APROX L= 400 FT, W= 5-6 FT
H= 5-6 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1355

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 13 LOOKING WEST
#2
#3
#4
#5

COMMENTS

NO SHORE

BR 50.00 #1



J101

INVENTORY NUMBER: 51.00

QUAD : BRANFORD
ADDRESS: SHORT BEACH
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION
MATERIAL : CONCRETE

DESCRIPTION

APROX L= 375 FT, W= 5 FT, H= 5 FT ABOVE MHW

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1401

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL


- PHOTOS -

#1 ROLL 44 NEG 14 LOOKING EAST
#2 ROLL 44 NEG 15 LOOKING WEST
#3
#4
#5

COMMENTS

SHORE: SANDY BEACH

SR 51.00 #1



SR 51.00 #2



INVENTORY NUMBER: 52.00

QUAD : BRANFORD
ADDRESS: 200 PAYNES POINT ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO CONCRETE. APROX L= 450 FT, W= 3 FT, H= 3-5 FT ABOVE
MHW.

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1406

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 44 NEG 16 LOOKING NORTH
#2 ROLL 44 NEG 17 LOOKING EAST
#3
#4
#5

COMMENTS

SHORE: SANDY BEACH

BR 52.00 #1



BR 52.00 #2



INVENTORY NUMBER: 53.00

QUAD : BRANFORD
ADDRESS: PAYNES POINT ROAD
TOWN : BRANFORD STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENTS EROSION, SERVES AS BASE FOR DOCK
MATERIAL : STONE IN CEMENT

DESCRIPTION

HAS CONCRETE CAP. APROX L= 75 FT, W= 7-10 FT, H= 3-5 FT
ABOVE MHW.

INSPECTION DATE : 08/12/88 INSPECTION TIME: 1423

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 44 NEG 18 LOOKING EAST
#2
#3
#4
#5

COMMENTS

SHORE: EXPOSED BEDROCK

SR 33.00 #1



J107

INVENTORY NUMBER: 54.00

QUAD : BRANFORD
ADDRESS: COSEY BEACH AVE
TOWN : EAST HAVEN STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: JETTY CONDITION: GOOD
MAIN FUNCTION : PREVENTS SHOALING OF CHANNEL
MATERIAL : LARGE BOULDERS

DESCRIPTION

APROX L=93 FT, W=28 FT, H=2-3 FT ABOVE MHW

INSPECTION DATE : 08/24/88 INSPECTION TIME: 1410

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE-FOUR BEACHES
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 45 NEG 2 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

BR 34.00 #1



J109

INVENTORY NUMBER: 55.00

QUAD : BRANFORD
ADDRESS: COSEY BEACH AVE
TOWN : EAST HAVEN STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

ALSO MADE OF STEEL AND LARGE BOULDERS
APROX L= 215 FT, W= 5-10 FT, H= 5-6 FT ABOVE MHW

INSPECTION DATE : 08/24/88 INSPECTION TIME: 1425

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PUBLIC
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 45 NEG 3 LOOKING WEST
#2
#3
#4
#5

COMMENTS

BR 65.00 #1



J111

INVENTORY NUMBER: 56.00

QUAD : BRANFORD
ADDRESS: FIRST AVE
TOWN : EAST HAVEN
COUNTY : NEW HAVEN

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: FAIR
MAIN FUNCTION : TRAPS LITTORAL DRIFT
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 64 FT, W= 12 FT, H= 0-2 FT ABOVE MHW

INSPECTION DATE : 08/24/88 INSPECTION TIME: 1430

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PUBLIC
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 45 NEG 4 LOOKING EAST
#2
#3
#4
#5

COMMENTS

BR 36.30 #1



J113

INVENTORY NUMBER: 57.00

QUAD : BRANFORD
ADDRESS: COSEY BEACH AVE
TOWN : EAST HAVEN STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: 3 GROINS CONDITION: FAIR
MAIN FUNCTION : TRAPS LITTORAL DRIFT
MATERIAL : STONE BLOCKS

DESCRIPTION

APROX L= 50 FT, W= 15 FT, H= 0-2 FT ABOVE MHW
APROX L= 54 FT, W= 20 FT, H= 0-1 FT ABOVE MHW
APROX L= 27 FT, W= 20 FT, H= 0-1 FT ABOVE MHW

INSPECTION DATE : 08/24/88 INSPECTION TIME: 1430

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE, MOMAUGUIN BEACH
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 45 NEG 5 LOOKING EAST
#2
#3
#4
#5

COMMENTS

BR 57.00 #1



J115

INVENTORY NUMBER: 58.00

QUAD : BRANFORD
ADDRESS: COSEY BEACH AVE
TOWN : EAST HAVEN STATE : CT
COUNTY : NEW HAVEN

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER
MATERIAL : CONCRETE

DESCRIPTION

ALSO STONE IN CEMENT
APROX L= 728 FT, W= 3 FT, H= 4-5 FT ABOVE MHW

INSPECTION DATE : 08/24/88 INSPECTION TIME: 1440

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 45 NEG 6 LOOKING WEST
#2
#3
#4
#5

COMMENTS

BR 58.00 #1



J117